1	2	3	4	5	6
166	1—00	1—00	166/1	10—04	4—00
166	21—15	4 —38	166/2	4—00	1—15
			166/3-1	1—00	1—00
			166 3-2	6—11	6—10
170/3	3—07	1—30	170/3	3—07	1—39
121/2	8—09	9—08	121/2	8—09	9—09
119/2	2—30	2—00	119/1	3—18	3—18
			119/2	2—31	2—30
119/3	2—30	2—11	119/3	2—11	2—11
118/2	10—37	8—20	118/1	4—04	3—20
			118/2	4—04	4—00
119/5-A	3—19	2—23	119-5A	3—17	2—23
			119/5B	3—19	3—19
This should be added			135/1	3—35	3—35
			135/2	4—00	4—00
			135/3	4—00	4—00
109/2	8—13	5—36			
143	16—12	7—14	These Sy. Nos. and area deleted.		
145	11—35	3—10			
11/2	4—04	3—04			

T. S. CHANDRASEKHAR.
2023 *Ex. Engr.*

Dated 18th June 1969.

CORRIGENDUM.

Sub:—Publication of Notification in respect of Tank at Todalbagi, Taluk Jamkhandi, District Bijapur.

No. IRR/CB/6572. In the Notification in respect of Minor Irrigation Tank at Todalbagi, Taluk Jamkhandi, District Bijapur published in Page 861, Part III-2 of English Gazette, dated 27th February 1969, some errors are noticed and some alterations to be made in the Gazette which may kindly be corrected as follows :—

As printed in the Gazette dated 27th February 1969.			To be corrected		
	For			*Read*	
	Todalbagi Village.			Todalbagi Village.	
Sy. No.	Area	Area benefited	Sy. No.	Total Area	Area benefited
466	14—35	13—39	466	14—35	13—30
471	21—35	29—00	471	21—35	20—00
472/2	12—29	12—00	472/4	12—20	12—00
463/3	3—2	3—0	462/3	3—2	3—00
	Hirep-adasalgi village.			Hirepadasalagi Village.	
54/1	11—09	11—00	54	22—29	22—17
54	11—08	11—00	64	11—08	11—00
57/4	4—36	4—00	57/4	3—00	3—00
49/1	4—07	4—00	40/1	4—07	4—00
58/1	5—15	5—10	58/1	4—07	4—00
59/1	3—32	3—39	59/1	3—22	3—20
59/1	3—07	3—06	50/1	3—07	3—06
49/2-B	7—27	7—29	49 2B	7—27	7—20
22/1	9—30	9—00	32/1	9—30	9—00
55/2	12—29	12—00	55/2	12—20	12—00
44/2A/2B	5—33	5—30	44/2A-2B	5—33	5—30
60/4-5	6—03	6—00	60/4	2—34	2—33
			60/5	3—00	2—38

1	2	3	4	5	6
60/1	4—07	4—00	60/1	4—37	4—35
60/3	3—08	3—00	60/3	5—36	5—34
42/4	6—30	6—26	42/4A	3—13	3—13
42/3	3—15	3—10	42/4B	3—17	3—17
45/3B	2—38	2—35	45/3B	2—16	2—12
45/1	5—05	5—00	45/1B	5—05	5—00
45/3A	2—39	2—35	45/3F	3—20	3—17
39/1B	6—00	5—35	39/1	5—07	5—07
39/1&2	16—10	16—00	39/2A	4—17	4—17
			39/2B	4—17	4—17
42/2	10—18	10—15	40/2	10—18	10—15
34	12—18	12—00	34	12—18	12—10
37	20—03	20—00	37/1	4—05	4—05
			37/2A/1	6—00	6—00
			37/2A/2	6—11	6—00
			37/2B	4—00	4—00
31	18—09	17—00	31	18—09	18—00
62/3	4—16	4—00	62/3	4—18	4—00
203/2B	3—20	3—15	203/3	3—03	2—38
203/2A	3—20	3—15	203/2	3—31	3—25
219/1	8—32	8—30	219/1A	4—00	4—00
			219/1B	4—08	4—08
			219/1C	4—08	4—08
			219/1D	3—04	3—04
			219/1E	6—17	6—12
219	8—00	7—35	This should be deleted		
219/1B	4—00	3—35			
205/2	3—15	3—10	205/2	14—10	13—01
205/1	20—00	19—00	205/1	4—16	3—25
218/2	5—27	5—20	218/2	20—00	19—30
208/1	13—35	23—30	208/1	13—29	13—25
			208/2	12—10	12—10
216	17—13	17—00	216	17—30	17—00
217/1	4—07	4—00	217/1	4—07	4—07
217/2	5—25	5—20	217/2	3—13	3—13
217/4	5—25	5—20	217/4A	5—26	5—26
217/5	5—00	4—35	217/3B	1—22	1—22
[illegible]			217/4B	4—22	4—22
			217/3A	1—22	1—22
221/A+B	21—10	21—0	221	29—39	29—00
222/2	5—18	5—10	222/2A	5—18	5—10

T. S. CHANDRASEKHAR,
Ex. Engr.

2023